


**Typ**  
**12A2**  
**S=20°**



**Příklad objednávky**

Typ	D	W	X	H	Zrnitost	Pojivo	Koncentrace
12 A2 = 20°	125	5	4	20	D126	K	75

D	W	X	H	T-X	E	K	J
50	3	Kovové pojivo 1-2-3-4 mm	Upínací otvor	8	6	29	15
50	5			8	6	25	15
50	6			8	6	23	15
75	3			8	6	54	34
75	5			8	6	50	34
75	6			8	6	48	34
75	10			8	6	40	34
100	3			10	8	79	48
100	5			10	8	75	48
100	6			10	8	73	48
100	7			10	8	71	48
100	8			10	8	69	48
100	10			10	8	65	48
125	3			14	8	74	51
125	5			14	8	70	51
125	6			14	8	68	51
125	7	14	8	66	51		
125	8	14	8	64	51		
125	10	14	8	60	51		
125	12,5	14	8	55	51		
150	5	Pryskyřičné pojivo 2-3-4 mm	Upínací otvor	16	9	88	65
150	6			16	9	86	65
150	10			16	9	78	65
150	12,5			16	9	73	65
150	15			16	9	68	65
175	5			18	10	105	79
175	6			18	10	103	79
175	10			18	10	95	79
175	15			18	10	85	79
200	5			20	12	130	93
200	10			20	12	120	93
200	15			20	12	110	93
250	3	23	13	169	126		
250	5	23	13	165	126		
250	10	23	13	155	126		
250	15	23	13	145	126		