


Typ
12A2
S=45°



Příklad objednávky

Typ	D	W	X	H	Zrnitost	Pojivo	Koncentrace
12 A2 = 45°	100	5	4	25	D151	K	100

D	W	X	H	T-X	E	K	J
75	3	Kovové pojivo 1-2-3-4 mm	Upínací otvor	20	10	41	37
75	5			20	10	37	37
75	6			20	10	35	37
75	10			20	10	39	37
100	3			22	10	61	58
100	5			22	10	57	58
100	6			22	10	61	58
100	7			22	10	59	59
100	8			22	10	57	58
100	10			22	10	57	58
100	15	Pryskyřičné pojivo 2-3-4-6 mm	Upínací otvor	22	10	47	58
125	3			22	10	86	83
125	5			22	10	82	83
125	6			22	10	86	83
125	7			22	10	84	83
125	8			22	10	82	83
125	10			22	10	82	83
125	12,5			22	10	77	83
125	15			22	10	72	83
150	5			22	12	107	108
150	6	22	12	105	108		
150	10	22	12	111	108		
150	12,5	22	12	106	108		
150	15	22	12	101	108		